

Unsold Lot Report For Auction: MLF - Excess Idle Assets

Lot Num.	Description	Seller
56C	Portable chemical cart Diversey (Located in Hamilton ON)	1
56D	Portable chemical cart Diversey (Located in Hamilton ON)	1
291B	(line 1) Loader Drake wiener loader mod. LS-1400 Ser. No. 09-671 stainless steel (Located in Hamilto	1
291C	(Line 1) Repidpak Thermoformer mod. RP-55 Ser. No. 855356 stainless steel c/w AB PanelView 1250 inte	1
3002	Microwave Single-Meal Tray Filling And Packaging Line incl.: (1) Ohlson s/s 6-channel vibratory port 2	2
3008	Videojet s/s 2-head ribbon printer (needs repair) (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR)	2
3012	Microwave Family-Meal Tray Filling And Packaging Line incl.:(1) small s/s frame conveyor(4) s/s hyd2	2
3031	steel worktable 36 in. x 72 in. c/w 5 in. vise (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Lo	2
3032	steel worktable 36 in. x 72 in. c/w vise (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located	2
3034	Salad Bowl Filling & Packaging Line INCL.:(1) s/s frame bowl filling conveyor line (2) sections (1)	2
3047	parts washer (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located in Brampton ON)	2
3058	Ridgid tri-stand #460 (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located in Brampton ON)	2
3064	1050 litre plastic liquid tote with w/ metal frame (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR)	2
3083	Mettler Toledo s/s checkweigher model Hi-Speed Micro-mate (MAY NOT BE COMPLETE REQUIRE2 PARTS AND/OR	2
3084	4-wheel steel hand truck (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located2 in Brampton ON)	2
3085	EcoLab air foamer cart (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located 2 in Brampton ON)	2
3088	CM Lodestar 1/8 ton electric chain hoist (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located	2
3089	(2) plastic drum tilters (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located in 2 Brampton ON)	2
3098	air receiver tank (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located in Brampton ON)	2
3119	Loveshaw Padlocker trayformer model 6.TSF ser. no. 3605 (2007) (MAY NOT BE COMPLETE REQUIRE PARTS AN	2
3129	(30) approx. warehouse overhead light fixtures (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Lo	2
4001	Soup Filling & Packaging Line incl.:(1) Packline (Nuspark) Soup Filling & Sealing Machine Mod. PXM-6	3
4036	Depositor Stainless Steel (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located in Kitchener O	3
4037	Femco Packaging Machine Mod. 3400-000-001 Ser. No. 8176 (2008) Stainless Steel (MAY NOT BE 3 COMPLETE	3
4052	Archi Filter System Mod. SIXK2.5F (2005) (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located	3
4063	CFS Blade Grinder Mod. USM300 Ser. No. 4040915792 (2008) (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR R	3
4068	Trojan Systems Wastewater UV Disinfection System Mod. UV3000 (MAY NOT BE COMPLETE REQUIRE PARTS AND/	3

Unsold Lot Report For Auction: MLF - Excess Idle Assets

Lot Num.	Description	Seller
4070	Z-Linker (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located in Kitchener ON)	3
4096	PPI Interleaver c/w 22 in. x 84 in. Conveyor (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Loca	3
4105	(2) Hydraulic Power Packs 7.5 Hp (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR)3 (Located in Kitch	3
4113	Belcor Case Taper Mod. Bel150 Ser. No. 00857 (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Loca	3
4114	Belcor Case Taper Mod. Bel151 Ser. No. 011071 (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Loc	3
4118	Buggy Dumper Stainless Steel on Casters (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located i	3
4131	Stainless Steel Conveyor w/ Wash Down Drive (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Locat	3
4142	Canada Ice Machine Refrigeration Coil (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located in	3
4150	Piston Stuffer Stainless Steel (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located in Kitch	3
4155	Belcor Case Taper Mod. Bel151 Ser. No. 011071 (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Loc	3
4166	Multivac Vacuum Packager Mod. R5200 Ser. No. 2028/100 (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPA	3
4172	(Lot) 2 Pumps (Disconnect Required) (MAY NOT BE COMPLETE REQUIRE PARTS AND/OR REPAIR) (Located in Ki	3

Number of Lots : 39